

# New York State Department of Transportation

## Yellow Flag NB22U4W001

By: Malav Shah

Flag Date: November 08, 2022

Superseding Information:

No Flags Superseded

### Structure Information

**BIN: 1065318**

**Feature Carried: 278I278IX2M23027**

**Feature Crossed: 6TH AVENUE**

**Orientation: 8 - NORTHWEST**

**Region: 11 - NEW YORK CITY**

**County: KINGS**

**Political Unit: City of NEW YORK**

**Approximate Year Built: 1962**

**Posted Load Matches Inventory : Yes**

**Bridge Load Posting (Tons) : Not Posted for Load**

**Primary Owner: New York State Department of Transportation**

**Primary Maintenance Responsibility: 12 - State - Subcontracted to another Party**

**Typical or Main Span Type: 3 - Steel, 02 - Stringer/Multi-Beam or Girder**

**This Bridge is not a Ramp**

**Number of Spans: 322**

### Verbal Notification Information

**Person Notified: Heinz Joachim, P.E.**

**Date: November 21, 2022 10:00:00 AM**

**Of: NYSDOT Region 11**

### Signature Information

**Signature: Malav Shah, P.E. 106620-1**

**Date: November 29, 2022**

**Reviewed By: Robert Kemp**

**Date: November 29, 2022**

**Attachments: 10**

**Flagged Elements**

Parent Element	Element	Total Quantity	Unit
<b>Span Number : 168</b>			
	107 - Steel Open Girder/Beam	729	ft
	PR831 - Steel Beam End	34	each

**Flagged Condition Description**

This Yellow Flag No. NB22U4W001 is NEW.

Location: Span 168, Girder G11 at Pier 167 located within scaffolding platforms installed by contractor which is located above parking lot between 38th and 39th Street.

Description:

The Girder G11 end at Pier 167 exhibits severe section loss with 0.3" – 0.475" remaining thickness measured (RTM) in the lower girder web in bearing area above bottom flange resulting in approximately 48% section loss. (Sketch 1, Photos 6, 8 & 9). Additionally, the bottom flange of the girder exhibits 30% to 45% section loss for 68"L for the full width of the flange (Sketch 1 & 2, Photo 8 & 9).

Although the overall shear web area section loss is approximately only 10%, the overall bearing area web section loss is approximately 48%. (refer to Yellow Flag Condition Sketch 1, Photo #2 for more details)

This is a newly flagged condition.

Notes:

1. Adjacent Girder G10 exhibits 34% section loss in the web area directly above the bearing. The lower web above the bottom flange exhibits up to 25% section loss. The remaining web height exhibits up to 15% section loss along the guide angle.
2. Adjacent Girder G12 exhibits up to 15% section loss along the guide angle and in the web area above bearing.
3. The bearing under Girder G11 exhibits 15% section loss to the bearing components.
4. Scaffolding platform was installed by contract within span at the time of inspection so single lane closure in the right lane on 3rd Avenue WB between 36th and 39th streets with 60 ft bucket truck was used to access platform.
5. The previous 2021 Biennial Report documented the above bearing location as CS3 with the following condition state note:  
Girder G11 exhibits an average localized section loss of 47% at the lower web for 10" high above the bottom flange with up to 20% section loss. The overall web bearing area section loss is approximately 35%.



**Flag Photographs**Photo Number: **1**Photo Filename: **FRAMING PLAN.png****Attachment Description: YELLOW FLAG LOCATION PLAN**

Photo Number: 2

Photo Filename: SKETCH 1\_R.jpg



LOCATION	RTM (in.)
1	0.7
2	0.73
3	0.73
4	0.68
5	0.32
6	0.63
7	0.32
8	0.28

**SPAN 168, GIRDER 11 AT PIER 167**  
**LEFT FACE (LOOKING RIGHT)**  
**N.T.S**

TRIBUTARY LENGTH CALC. FOR SHEAR AREA			
	ABOVE (in.)	BELOW (in.)	TOTAL (in.)
FOR POINT 1	6	2.25	8.25
FOR POINT 2	2.25	2.5	4.75
FOR POINT 3	2.5	1.75	4.25
FOR POINT 4	1.75	3	4.75
FOR POINT 6	3	4	7

**Section Loss Calculations:**

Original girder web thickness = 0.77" (measured)

Localized section loss in web area above bearing =  $(0.77" - 0.3") / 0.77" \times 100 = 61\%$  section loss

Web bearing area length =  $18 \times 0.77" = 13.86"$

Web bearing area =  $[ \{ ((0.32+0.28)/2) \times 6" \} + [ \{ ((0.32+0.63)/2) \} \times 7.86" ] = 5.53 \text{ in}^2$

Overall web bearing area section loss =  $[ \{ (13.86" \times 0.77") - 5.53 \text{ in}^2 \} / (13.86" \times 0.77") ] \times 100 = 48\%$  section loss

Shear web area =  $(0.7" \times 8.25") + (0.73" \times 4.75") + (0.73" \times 4.25") + (0.68" \times 4.75") + (0.63" \times 7") = 19.985 \text{ in}^2 \sim \text{Say } 20 \text{ in}^2$


Overall shear web area section =  $[ (0.77" \times 29") - 20 \text{ in}^2 ] / (0.77" \times 29") \times 100\% = 10.4\%$  section loss

**Attachment Description: YELLOW FLAG CONDITION SKETCH 1**



Photo Number: 3


Photo Filename: SKETCH 2.jpg



**Attachment Description: YELLOW FLAG CONDITION SKETCH 2**

Photo Number: 4

Photo Filename: GENERAL VIEW.PNG



**Attachment Description:** General view of flagged condition at Girder G11 in Span 168 at Pier 167 (located above the installed shielding platform). Looking Begin - Left

Photo Number: 5

Photo Filename: G11\_GV\_LF.PNG



**Attachment Description:** General view of Girder G11 in Span 168 at Pier 167. Looking Begin and Right.



Photo Number: 6

Photo Filename: G11 GV\_RF.PNG



**Attachment Description:** General view of Girder G11 in Span 168 at Pier 167. Looking Begin and Left.

Photo Number: 7

Photo Filename: G11\_LF.PNG



**Attachment Description:** Close-up general view of Girder G11 in Span 168 at Pier 167. The end of Girder G11 exhibits severe section loss ( approximately 48% section loss) in the lower girder web bearing area above the bottom flange. Additionally, the bottom flange of the girder exhibits 30% to 45% section loss for 68"L for the full width of the flange. Looking Right.



Photo Number: 8

Photo Filename: G11\_RF.PNG



**Attachment Description:** Close-up general view of Girder G11 in Span 168 at Pier 167. The end of Girder G11 exhibits severe section loss ( approximately 48% section loss) in the lower girder web bearing area above the bottom flange. Additionally, the bottom flange of the girder exhibits 30% to 45% section loss for 68"L for the full width of the flange. Looking Left.

Photo Number: 9

Photo Filename: G11 CLOSE UP VIEW\_LF.PNG



**Attachment Description:** The Girder G11 End exhibits severe section loss ( approximately 48% section loss) in the lower girder web in bearing area above bottom flange. The bottom flange of the girder on left face exhibits 30% to 45% section loss for 68"L for the full width of the flange. Looking Right.



Photo Number: 10

Photo Filename: G11 CLOSE UP VIEW\_RF.PNG



**Attachment Description:** The end of Girder G11 exhibits severe section loss ( approximately 48% section loss) in the lower girder web in bearing area above bottom flange. The bottom flange of the girder on left face exhibits 30% to 45% section loss for 68"L for the full width of the flange. Looking Left.